

Woodstock, GA 30188 U.S.A.

NO: 551684-00	REV:	PAGE: 1 of 1	DATE ISSUED: 10/15/2008
WRITTEN BY: MK	DATE: 10/1/2008	APPROVED BY: TG	DATE: 10/3/2008
SUBJECT: KR215/219 Belt tension adjustment with KR837 Divert			

As of June 2008 we have added two L-shaped brackets to support the divert gate on the KR215 and KR219 bases.

These brackets must be loosened where they attach to the divert gate before adjusting the belt tension.

Failure to do so will not allow the roller to adjust and may cause the adjustment screw to break.

